

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
DEL,
2 - WILM.V,
4 -

West Brandywine Grange
4008 Concord Pike
Wilmington Vicinity
New Castle County
Delaware

HABS No. DE-236

Photographer: David Ames, September 22, 1985

- DE- 236 -1 PERSPECTIVE ON EAST FRONT AND SOUTH SIDE LOOKING
WEST-NORTHWEST
- DE- 236 -2 PERSPECTIVE ON WEST REAR AND NORTH SIDE LOOKING EAST-
SOUTHEAST
- DE- 236 -3 DETAIL OF FRONT DOOR LOOKING WEST
- DE- 236 -4 DETAIL OF FRONT PORCH ROOF FRAMING LOOKING NORTH
- DE- 236 -5 FIRST FLOOR VESTIBULE ON EAST SIDE LOOKING SOUTH
- DE- 236 -6 FIRST FLOOR VESTIBULE, DETAIL OF MOLDING AND DOOR
SURROUND ON WEST WALL LOOKING WEST
- DE- 236 -7 FIRST FLOOR MEETING HALL LOOKING WEST
- DE- 236 -8 FIRST FLOOR KITCHEN ON WEST SIDE LOOKING SOUTH
- DE- 236 -9 FIRST FLOOR KITCHEN, MEETING HALL AND VESTIBULE
LOOKING EAST
- DE- 236 -10 SECOND FLOOR MEETING HALL, LOOKING WEST
- DE- 236 -11 SECOND FLOOR MEETING HALL LOOKING EAST
- DE- 236 -12 SECOND FLOOR, DETAIL ON BACK OF DOOR TO HALL OF
ENTRY BELL AND PEEP HOLE LOOKING SOUTH
- DE- 236 -13 ATTIC: RAFTERS LOOKING WEST